



PROJECT & SITE

CLIENT Cabot Creamery	PROJECT Pathogen Surveillance — Cheddar Line	PROJECT CODE CABOT-PATH-26	STATE VT
SITE NAME Cheddar Line — Drain D-4	SITE CODE CABOT-CL-D4	SITE TYPE food facility	GPS 44.5089, -72.3003

SAMPLING EVENT

SAMPLER Maria Gonzalez	COLLECTED 6/5/2026, 8:32:51 PM	WEATHER Light rain	AIR TEMP 22.8 °C	RECEIPT TEMP 3.4 °C
---------------------------	-----------------------------------	-----------------------	---------------------	------------------------

FIELD READINGS AT COLLECTION

PH 6.83	COND. (µS/CM) 650	DO (MG/L) 5.55	TEMP (°C) 16.0	ORP (MV) 123	TURB. (NTU) 3.69
------------	----------------------	-------------------	-------------------	-----------------	---------------------

SHIPPING & COOLER RECEIPT

CARRIER Client	TRACKING —	COOLER ID CLR-700	COOLER TEMP BLANK 5.0 °C	STATUS SEALED
TAMPER SEALS 100663,100664	SEALS INTACT YES	# CONTAINERS 1	SEALED 6/5/2026, 8:32:51 PM	

SAMPLE CONTAINERS

ACCESSION	CONTAINER	PRES.	MATRIX	VOL (ML/G)	RECEIPT COND.	PH CHK	PRES. OK	TESTS REQUESTED
ENV-2026-04687	Sterile sample bag	iced	FOOD	25	INTACT	n/a	YES	ISO 6579, ISO 11290-1

CHAIN OF CUSTODY TRANSFERS

#	RELINQUISHED BY	DATE / TIME	SIGNATURE	RECEIVED BY	DATE / TIME	SIGNATURE
1	Maria Gonzalez	6/5/2026, 11:32:51 PM	Maria Gonzalez	Endyne Courier	6/6/2026, 12:06:37 AM	T. Hill

LABORATORY ACCEPTANCE

Harry Locker

ENDYNE LAB RECEIVING · 6/5/2026, 8:32:51 PM

WITNESS · DATE

This Chain of Custody record documents possession of samples from collection through final analytical result. This report shall not be reproduced except in full, without the written approval of Endyne Inc. Results reported relate only to items tested. Test results meet all requirements of ISO/IEC 17025:2017 and applicable state/EPA accreditation programs except as noted in the Case Narrative.