



PROJECT & SITE

CLIENT	PROJECT	PROJECT CODE	STATE
Burlington Department of Public Works	PFAS Source Investigation — North End	BURL-PFAS-2026	VT
SITE NAME	SITE CODE	SITE TYPE	GPS
North End Test Boring TB-04	BURL-PFAS-TB4	soil boring	44.4951, -73.2114

SAMPLING EVENT

SAMPLER	COLLECTED	WEATHER	AIR TEMP	RECEIPT TEMP
Maria Gonzalez	5/22/2026, 11:32:51 PM	Light rain	18.3 °C	4.0 °C

FIELD READINGS AT COLLECTION

PH	COND. (µS/CM)	DO (MG/L)	TEMP (°C)	ORP (MV)	TURB. (NTU)
7.79	779	7.47	19.1	142	1.78

SHIPPING & COOLER RECEIPT

CARRIER	TRACKING	COOLER ID	COOLER TEMP BLANK	STATUS
FedEx	7522310267412	CLR-293	3.7 °C	SEALED
TAMPER SEALS	SEALS INTACT	# CONTAINERS	SEALED	
100675,100676	YES	1	5/22/2026, 11:32:51 PM	

SAMPLE CONTAINERS

ACCESSION	CONTAINER	PRES.	MATRIX	VOL (ML/G)	RECEIPT COND.	PH CHK	PRES. OK	TESTS REQUESTED
ENV-2026-04698	250mL polypropylene	iced	SOIL	250	INTACT	n/a	YES	EPA 537.1

CHAIN OF CUSTODY TRANSFERS

#	RELINQUISHED BY	DATE / TIME	SIGNATURE	RECEIVED BY	DATE / TIME	SIGNATURE
1	Maria Gonzalez	5/23/2026, 3:32:51 AM	Maria Gonzalez	Endyne Courier	5/23/2026, 4:24:22 AM	T. Hill

LABORATORY ACCEPTANCE

Harry Locker

ENDYNE LAB RECEIVING · 5/22/2026, 11:32:51 PM

WITNESS · DATE

This Chain of Custody record documents possession of samples from collection through final analytical result. This report shall not be reproduced except in full, without the written approval of Endyne Inc. Results reported relate only to items tested. Test results meet all requirements of ISO/IEC 17025:2017 and applicable state/EPA accreditation programs except as noted in the Case Narrative.