



**PROJECT & SITE**

CLIENT	PROJECT	PROJECT CODE	STATE
Burlington Department of Public Works	Wastewater NPDES Compliance	BURL-NPDES	VT
SITE NAME	SITE CODE	SITE TYPE	GPS
Main WWTP Outfall 001	BURL-WWTP-001	wastewater discharge	44.4709, -73.2208

**SAMPLING EVENT**

SAMPLER	COLLECTED	WEATHER	AIR TEMP	RECEIPT TEMP
Maria Gonzalez	5/22/2026, 2:32:51 AM	Snow	-1.7 °C	3.2 °C

**FIELD READINGS AT COLLECTION**

PH	COND. (µS/CM)	DO (MG/L)	TEMP (°C)	ORP (MV)	TURB. (NTU)
6.97	236	6.88	12.3	148	3.05

**GROUNDWATER PURGE LOG**

PURGE VOLUME (L)	DRAWDOWN (M)	PUMP RATE	STABILIZED
19.6	0.43	0.5 L/min	3 well volumes

**SHIPPING & COOLER RECEIPT**

CARRIER	TRACKING	COOLER ID	COOLER TEMP	BLANK	STATUS
Client	—	CLR-480	3.6 °C		SEALED
TAMPER SEALS		SEALS INTACT	# CONTAINERS		SEALED
100685,100686		YES	2		5/22/2026, 2:32:51 AM

**SAMPLE CONTAINERS**

ACCESSION	CONTAINER	PRES.	MATRIX	VOL (ML/G)	RECEIPT COND.	PH	CHK	PRES. OK	TESTS REQUESTED
ENV-2026-04708	1L plastic	iced	WASTE-WATER	1000	INTACT	n/a		YES	SM 5210B, SM 2540D
ENV-2026-04709	250mL HDPE	HNO3	WASTE-WATER	250	INTACT	1.4		YES	EPA 6020B

**CHAIN OF CUSTODY TRANSFERS**

#	RELINQUISHED BY	DATE / TIME	SIGNATURE	RECEIVED BY	DATE / TIME	SIGNATURE
1	Maria Gonzalez	5/22/2026, 6:32:51 AM	Maria Gonzalez	Endyne Courier	5/22/2026, 7:11:16 AM	T. Hill

**LABORATORY ACCEPTANCE**

*Harry Locker*

ENDYNE LAB RECEIVING · 5/22/2026, 2:32:51 AM

WITNESS · DATE

*This Chain of Custody record documents possession of samples from collection through final analytical result. This report shall not be reproduced except in full, without the written approval of Endyne Inc. Results reported relate only to items tested. Test results meet all requirements of ISO/IEC 17025:2017 and applicable state/EPA accreditation programs except as noted in the Case Narrative.*